



2141 ICON Way, Vacaville, CA 95688 - Tel: 707.564.4000 – www.iconaircraft.com

SERVICE LETTER

SL-051622 REV A

DATE ISSUED: 05/16/2022

DATE EFFECTIVE: 05/16/2022

SUBJECT: Redressal of ROTAX SL-912i-005R2 use of non-ROTAX replacement parts.

AIRCRAFT AFFECTED: **MODEL:** A5

S/N: All

REQUIRED ACTION: 1. If a part (or parts) replacement is required during a service inspection or repair of the ROTAX 912iS engine, verify that the part (or parts) is approved ROTAX replacement part (or parts).

TIME OF COMPLIANCE: Refer to ROTAX SL-912i-005R2, Section 1.5:

- NONE – For information only

PURPOSE: The use of any third-party after-market replacement kits, modifications and non-genuine ROTAX® components or accessories is not approved by ROTAX® and may result in engine damage and/or engine failure resulting in personal injury and/or death.

WARRANTY

Refer to ROTAX SL-912i-005R2, section 1.7 for labor and time credit.

PARTS LIST:

PART	DESCRIPTION	A5
(Refer to SL-912i-005R2)		

INSTRUCTIONS:

Please refer to the attached ROTAX Service Letter SL-912i-005R2 dated 13 May 2022.

Make the following logbook entry:

None

If you have questions, comments, or concerns about this Safety Letter and/or if you are no longer owner/operator of this aircraft, please forward this information to the present owner/operator and notify ICON Aircraft at:

ICON Aircraft
 2141 ICON Way, Ste 100
 Vacaville, CA 95688
 (855) FLY-ICON or (707) 564-4000
support@iconaircraft.com

Please include the aircraft registration number, serial number, your name, and if known the contact information of the new owner/operator.